

Pasco County Utilities Emergency Rule Notification

- Installation Name: **Shady Hills Wastewater Treatment Facility**
- Installation Address: **14220 Hays Road, Spring Hill, FL 34610**
- For further information, contact James Hircock, Environmental Compliance Specialist,
727-457-0358 (Cell) or 813-247-0391 (PTT)
- Permit Number (if applicable): **FLA012741**
- Date and time of the incident or discovery: **DATE: 4 June 2017 TIME: 1:45 AM**
- Location of the incident or discovery: **14220 Hays Road, Shady Hills WWTP**
- Suspected source and cause of incident or discovery: **Treated (Not Chlorinated) Domestic . the fill valve on the crom tank supplying the W-3 system did not close when tank reached high level. The on-site operator noticed the problem when the tank was overflowing from the vents on the top of tank.**
- Type of pollution, including substance or contaminant name(s): **Treated (Non-Chlorinated) domestic waste.**
- Estimate amount of pollution, including substance or contaminant name(s): **Approximately 10,000 Gallons of treated (Non-Chlorinated) domestic waste (0 gallons recovered)**
- Source: (e.g. land, water, air) affected: **LAND: X WATER: _____ AIR: _____**
- potentially affected areas beyond installation property boundary: **NONE, 10,0000 gallons went onto the ground and absorbed into the from overflow of the Crom Tank due to fill valve malfuction.**
- Potential risk (public health, safety, or welfare): **High ___ Medium ___ Low ___ None X**
- Identification of other parties notified of incident and time notification occurred:
 - Name: **(FDEP) Ileana Hernandez** Time Notified: **(24 Hour) X (48 Hour)**
 - Name: **(Daniel Biles)** Time Notified: **(24 Hour) (48 Hour)**
 - Name: **(Douglas Tobin)** Time Notified: **(24 Hour) (48 Hour)**
 - Name: **(Flip Mellinger)** Time Notified: **(24 Hour) (48 Hour)**
 - Name: **(Mike Moore–BOCC Chairman)** Time Notified: **(24 Hour) (48 Hour)**
 - Name: **(ALL Directors) Michael Carballa** Time Notified: **(24 Hour) X (48 Hour)**
- Additional information that may be helpful: **MAP # 269, SSO # 836, NO further action needed. Mechanic will investigate the malfunction.**