Pasco County Utilities Emergency Rule Notification

□ Installation Name: Embassy Hills Wastewater Treatment Facility
☐ Installation Address: 9512 Crab Tree Lane, Port Richey, FL 34668
☐ For further information, contact James Hircock, Environmental Compliance Specialist,
727-457-0358 (Cell) or 813-247-0391 (PTT)
□ Permit Number (if applicable): <u>FLA012735</u>
□ Date and time of the incident or discovery: DATE: 9 June 2017 TIME: 2:00 PM
□ Location of the incident or discovery: <u>14220 Hays Road, Shady Hills WWTP</u>
□ Suspected source and cause of incident or discovery: Damaged F/M 4" knock on coupler failed causing the leak. Removed damaged coupler and made a repair using a 4" full
<u>circle.</u> ☐ Type of pollution, including substance or contaminant name(s): <u>Untreated domestic waste.</u>
□ Estimate amount of pollution, including substance or contaminant name(s): Approximately 30 Gallons (1 GPM for 30 minutes) of untreated domestic waste (0 gallons recovered). Restored site with lime rock and millings. Spread approx. 2 lbs. of lime in the Miami curb.
□ Source: (e.g. land, water, air) affected: LAND:X WATER: AIR:
□ potentially affected areas beyond installation property boundary: NONE, 30 gallons went onto the ground. Was unable to retrieve any liquids from site due to evaporation.
□ Potential risk (public health, safety, or welfare): High Medium Low None _X_
☐ Identification of other parties notified of incident and time notification occurred:
Name: (FDEP) Ileana Hernandez Time Notified: (24 Hour) X (48 Hour)
Name: (Daniel Biles) Time Notified: (24 Hour) (48 Hour)
Name: (Douglas Tobin) Time Notified: (24 Hour) (48 Hour)
Name: (Flip Mellinger) Time Notified: (24 Hour) (48 Hour)
Name: (Mike Moore-BOCC Chairman) Time Notified: (24 Hour) (48 Hour)
Name: (ALL Directors) Rob Marin Time Notified: (24 Hour) X (48 Hour)
□ Additional information that may be helpful: MAP # 87, W/O # 559828, SSO # 838